- (b) For surface type units, the maneuvering information in Subpart 97.19 of this chapter must be displayed.
- (c) The maneuvering information requirements for column stabilized, self-elevating, and other units of unusual design will be specified on a case by case basis.

§ 109.565 Charts and nautical publications.

The master or person in charge of a self-propelled unit shall ensure that the unit has the following adequate, up to date, and appropriate items for the intended voyage:

- (a) Charts.
- (b) Sailing directions.
- (c) Coast pilots.
- (d) Light lists.
- (e) Notices to mariners.
- (f) Tide Tables.
- (g) Current Tables.
- (h) All other nautical publications necessary. $^{\rm 1}$

§ 109.573 Riveting, welding, and burning operations.

Except as allowed by this section—

- (a) The master or person in charge shall ensure that there is no riveting, welding, or burning—
 - (1) In a fuel tank;
 - (2) On the boundary of a fuel tank;
- (3) On pipelines, heating coils, pumps, fittings, or other appurtenances connected to fuel tanks; or
- (4) On the boundary of spaces adjacent to tanks carrying Grades A, B, or C flammable liquids in bulk.
- (b) The operations prohibited in paragraph (a) of this section may be allowed if—
- (1) An inspection conducted in accordance with the "Standard for the Control of Gas Hazards on Vessels to be Repaired," N.F.P.A. No. 306–1974, is made—
- (i) In ports or navigable waters of the United States, its territories and possessions, by—
- (A) A marine chemist certified by the National Fire Protection Association; or
- (B) If a certified marine chemist is not available, a person designated by

¹NOTE: For U.S. units in or on the navigable waters of the United States. See 33 CFR 164 33

the Officer in Charge, Marine Inspection; or

- (ii) In all other locations by-
- (A) A marine chemist certified by the National Fire Protection Association:
- (B) If a certified marine chemist is not available, a person designated by the Officer in Charge, Marine Inspection; or
- (C) If the persons required in paragraphs (b)(1)(ii) (A) and (B) of this section are not available, the master or person in charge; or a welding supervisor designated, in writing, by the master or person in charge; and
- (2) A certificate is issued by the person conducting the inspection stating—
- (i) That he conducted the inspection in accordance with the standard in paragraph (b)(1) of this section;
- (ii) The operations that may be conducted; and
- (iii) A list of precautions to be followed during the operations;
- (c) The master or person in charge shall ensure that the precautions in paragraph (b)(2)(iii) of this section are followed.

§ 109.575 Accumulation of liquids on helicopter decks.

The master or person in charge shall ensure that no liquids are allowed to accumulate on the helicopter decks.

§ 109.577 Helicopter fueling.

- (a) The master or person in charge shall designate persons to conduct helicopter fueling operations.
- (b) Portable tanks are handled and stowed in accordance with subparts 98.30 and 98.33 of this chapter and the provisions of 49 CFR parts 171 through 179 that apply to portable tanks; and

[CGD 73-251, 43 FR 56828, Dec. 4, 1978, as amended by CGD 84-043, 55 FR 37413, Sept. 11, 1990]

§ 109.585 Use of auto pilot.

Except as provided in 33 CFR 164.15, when the automatic pilot is used in areas of high traffic density, conditions of restricted visibility, and all other hazardous navigational situations, the master or person in charge shall ensure that—

(a) It is possible to immediately establish manual control of the unit's steering: